




# Service Parts Database

Service Parts Database — Part #1 of 79 Found

661-0345

Floppy Drive, 800K Mechanism, 3.5"



## Notes:

The drive warranty will be void and Apple will return the module to the service provider without repair if the drive bar code label, manufacturer identification label, Apple capacity or EPROM label, or labels that say "Warranty Void If Seal Is Broken" have been tampered with or removed.

When returning the floppy drive to Apple, remove the internal drive cable and assemble the shipping fixture and the packing disk as shown.

All drives must be shipped in Apple packaging; when returning a defective drive, use the exchange module's packaging. Failure to comply with this requirement may result in a packaging noncompliance charge.

## Warranty Return Notes:

This drive can be readily identified by its red-on-silver label.

## Products Where Used:

Apple 3.5 Drive  
Apple IIc Plus  
Macintosh 128K / 512K / 512Ke  
Macintosh Disk Drive  
Macintosh II  
Macintosh Plus  
Macintosh SE  
UniDisk 3.5