




Service Parts Database

Service Parts Database — Part #1 of 79 Found

661-76156

Floppy Drive, 400K Mechanism, 3.5"



Notes:

The drive warranty will be void and Apple will return the module to the service provider without repair if the drive bar code label, manufacturer identification label, Apple capacity or EPROM label, or labels that say "Warranty Void If Seal Is Broken" have been tampered with or removed.

All drives must be shipped in Apple packaging; when returning a defective drive, use the exchange module's packaging. Failure to comply with this requirement may result in a packaging noncompliance charge.

Return drives without cables or carriers.

Warranty Return Notes:

The shield was removed on later versions of this mechanism.

Products Where Used:

Macintosh 128K / 512K / 512Ke

Macintosh Disk Drive